



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	138	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6119		Western Run	DR

Source Type:	02= Service Line	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	80	

Comments:

SMOKE TEST PHOTOS



Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_B\B_2004_1004Image0014.JPG

Image Status: Image found and displayed.



Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_B\B_2004_1004Image0015.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 138

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\138.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	138	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	8	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6201		Western Run	DR

Source Type:	02= Service Line	Location:	6=Curb	Severity:
Sector:	1=Public	Drainage Area:	20	

Comments:

SMOKE TEST PHOTOS



Photo No: 16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_B\B_2004_1004Image0016.JPG

Image Status: Image found and displayed.



Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_B\B_2004_1004Image0017.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 138

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\138.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	138	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	B	Crew:	T-1	Dye Test Recommended:	N
Defect No:	9	Setup No:	1	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
2824		Taney	ROAD

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	300	

Comments:

SMOKE TEST PHOTOS



Photo No: 18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_B\B_2004_1004Image0018.JPG

Image Status: Image found and displayed.



Photo No: 19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_B\B_2004_1004Image0019.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 138

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\138.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	139	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	1	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6001		Baywood	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	75	

Comments:

SMOKE TEST PHOTOS




Photo No: 9

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0009.JPG

Image Status: Image found and displayed.



Photo No: 10

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0010.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 139

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\139.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	139	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	2	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6003		Baywood	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	0	

Comments:

SMOKE TEST PHOTOS



Photo No: 11

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0011.JPG

Image Status: Image found and displayed.



Photo No: 12

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0012.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 139

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\139.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	139	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	3	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6012		Baywood	AVE

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	75	

Comments:

SMOKE TEST PHOTOS



Photo No: 13

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0013.JPG

Image Status: Image found and displayed.



Photo No: 14

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0014.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 139

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\139.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	139	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	4	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6003		Western Run	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	75	

Comments:

SMOKE TEST PHOTOS



Photo No: 15

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0015.JPG

Image Status: Image found and displayed.



Photo No: 16

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0016.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 139

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\139.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	139	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	5	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6005		Western Run	DR

Source Type:	04= Cleanout	Location:	7=Yard-Front	Severity:
Sector:	2=Private	Drainage Area:	25	

Comments:

SMOKE TEST PHOTOS



Photo No: 17

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0017.JPG

Image Status: Image found and displayed.



Photo No: 18

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0018.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 139

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\139.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	139	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	6	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6005		Western Run	DR

Source Type:	12= MH Frame Seal	Location:	5=Sidewalk	Severity:
Sector:	1=Public	Drainage Area:	100	

Comments:

SMOKE TEST PHOTOS




Photo No: 19

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0019.JPG

Image Status: Image found and displayed.



Photo No: 20

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0020.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 139

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\139.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

Unique Test ID	139	Date:	10/4/2004	MeterBasin:	01_WRR05
Observer ID:	A	Crew:	T-1	Dye Test Recommended:	N
Defect No:	7	Setup No:	2	Priority CCTV:	

House Number	Street Prefix:	Street Name:	Street Type:
6005		Western Run	DR

Source Type:	12= MH Frame Seal	Location:	2=Paved Asphalt	Severity:
Sector:	1=Public	Drainage Area:	4200	
Comments:	MH 1520867			

SMOKE TEST PHOTOS



Photo No: 21

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0021.JPG

Image Status: Image found and displayed.



Photo No: 22

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke
Testing\Pictures\1004-2004\T-1\PLAYER_A\A_2004_1004Image0022.JPG

Image Status: Image found and displayed.

Photo No:

Filename Path:


Image Status: No image name specified.



SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

FIELD SKETCH



Sketch No: 139

Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\139.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.